

Dimensions of B008 4-Jaw Chuck for Metal Lathe

$D = 6\frac{1}{4}$.

$D1 = 5\frac{3}{32}$.

$D2 = 5\frac{25}{32}$.

$D3 = 1\frac{35}{64}$.

$H = 17\frac{1}{64}$.

$H = 2\frac{39}{64}$.

